



**CONSTRUCTION NOTES:**

1. REMOVE AND REPLACE RAMP
2. REMOVE AND REPLACE RAMP WITH 5' LONG RAMP
3. REMOVE AND REPLACE RAMP WITH DIRECTIONAL RAMP
4. REPAIR AND REPLACE PCC SIDEWALK, 20 SY
5. ADD PCC SIDEWALK, 6 SY
6. REPAIR AND REPLACE PCC SIDEWALK, 18 SY
7. REPAIR AND REPLACE PCC SIDEWALK, 22 SY
8. ADD POROUS FLEXIBLE PAVING, 10 SY
9. REPAIR AND REPLACE PCC SIDEWALK, 10 SY
10. REPAIR AND REPLACE PCC SIDEWALK, 26 SY
11. REPAIR AND REPLACE PCC SIDEWALK, 9 SY
12. ADD PCC SIDEWALK, 91 SY
13. ADJUST STANDARD BASIN TOP



<b>LEGEND</b>	EXISTING CONDITIONS	PCC SIDEWALK
	PROPOSED CONDITIONS	BRICK SIDEWALK
	EXISTING TRAFFIC SIGNAL CABINET	GRASS
	EXISTING PEDESTRIAN SIGNAL	DETECTABLE WARNING SURFACE

**The Temple Group, Inc.**  
 1120 Connecticut Avenue, NW  
 Suite 310  
 Washington, DC 20036  
 Ph.: 202-822-6600  
 Fax: 202-822-6603  
 www.thetemplegroup.com

No.	DESCRIPTION	NAME	DATE
REVISIONS			

DISTRICT OF COLUMBIA  
 DEPARTMENT OF TRANSPORTATION  
 INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION

**CITY-WIDE AMERICANS WITH  
 DISABILITIES ACT COMPLIANCE**  
 DCKA-2011-C-0059

14TH ST. AT UNDERWOOD ST., NW  
 BUS STOP #1002780, 1002781

PROJECT ENG.	AK
DESIGN BY	AK
CHECKED BY	AK
DRAWN BY	VMD
FILE	
DATE	01/27/14
SHEET	01 OF 01
DWG NO.	