

- CONSTRUCTION NOTES:**
1. REMOVE AND REPLACE RAMP
  2. REMOVE AND REPLACE RAMP WITH 5' LONG RAMP
  3. REPAIR AND REPLACE PCC SIDEWALK, 18' X 15'
  4. REPAIR AND REPLACE PCC SIDEWALK, 16' X 15'
  5. ADD PCC SIDEWALK, 30' X 6'
  6. ADD PCC SIDEWALK, 21' X 5'
  7. REPAIR AND REPLACE PCC SIDEWALK, 19' X 16'
  8. REPAIR AND REPLACE PCC SIDEWALK, 101' X 6'
  9. ADD PCC SIDEWALK, 50' X 1.5'
  10. REPAIR AND REPLACE PCC SIDEWALK, 15' X 5'
  11. ADD PCC SIDEWALK, 7' X 2'



|               |                                 |                            |
|---------------|---------------------------------|----------------------------|
| <b>LEGEND</b> | EXISTING CONDITIONS             | PCC SIDEWALK               |
|               | PROPOSED CONDITIONS             | BRICK SIDEWALK             |
|               | EXISTING TRAFFIC SIGNAL CABINET | GRASS                      |
|               | EXISTING PEDESTRIAN SIGNAL      | DETECTABLE WARNING SURFACE |

**The Temple Group, Inc.**  
 1120 Connecticut Avenue, NW  
 Suite 310  
 Washington, DC 20036  
 Ph.: 202-822-6600  
 Fax: 202-822-6603  
 www.thetemplegroup.com


| No.       | DESCRIPTION | NAME | DATE |
|-----------|-------------|------|------|
| REVISIONS |             |      |      |

DISTRICT OF COLUMBIA  
 DEPARTMENT OF TRANSPORTATION  
 INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION

**CITY-WIDE AMERICANS WITH  
 DISABILITIES ACT COMPLIANCE**  
 DCKA-2011-C-0059

7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE  
 BUS STOP #1001960, 1001966,  
 1002104, 1002028, 1002035

|              |          |
|--------------|----------|
| PROJECT ENG. | AK       |
| DESIGN BY    | AK       |
| CHECKED BY   | AK       |
| DRAWN BY     | VMD      |
| FILE         |          |
| DATE         | 02/28/14 |
| SHEET        | 01 OF 03 |
| DWG NO.      |          |



HOLY REDEEMER  
COLLEGE

CENTRO MARIA  
RELIGIOUS OF  
MARY IMMACULATE

7TH ST.

7TH ST.

BUS STOP #1002028

BUS STOP #1002035

7TH ST.

2

2

4

SMALL STONE FENCE

IRVING ST.

9

8

2

2

JACKSON ST.

2

2

4

5

1

2

6

7



**CONSTRUCTION NOTES:**

1. REMOVE AND REPLACE RAMP WITH DIRECTIONAL RAMP
2. REMOVE AND REPLACE RAMP WITH 5' LONG DIRECTIONAL RAMP
3. REPAIR AND REPLACE PCC SIDEWALK, 12' X 12'
4. REPAIR AND REPLACE PCC SIDEWALK, 14' X 13'
5. REPAIR AND REPLACE PCC SIDEWALK, 14' X 14'
6. REPAIR AND REPLACE PCC SIDEWALK, 16' X 12'
7. ADD PCC SIDEWALK, 40' X 6'
8. REPAIR AND REPLACE PCC SIDEWALK, 47' X 12'
9. ADD PCC SIDEWALK, 20' X 6'


|   |  |
|---|--|
| DISTRICT OF COLUMBIA<br><b>DEPARTMENT OF TRANSPORTATION</b><br>INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION |  |
| <b>CITY-WIDE AMERICANS WITH<br/>         DISABILITIES ACT COMPLIANCE</b><br>DCKA-2011-C-0059                    |  |
| 7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE<br>BUS STOP #1001960, 1001966,<br>1002104, 1002028, 1002035           | PROJECT ENG. <u>AK</u><br>DESIGN BY <u>AK</u><br>CHECKED BY <u>AK</u><br>DRAWN BY <u>VMD</u> |
| FILE _____<br>DATE <u>02/28/14</u><br>SHEET <u>02 OF 03</u><br>DWG NO. _____                                    |  |

|               |  |                                 |  |                            |
|---------------|--|---------------------------------|--|----------------------------|
| <b>LEGEND</b> |  | EXISTING CONDITIONS             |  | PCC SIDEWALK               |
|               |  | PROPOSED CONDITIONS             |  | BRICK SIDEWALK             |
|               |  | EXISTING TRAFFIC SIGNAL CABINET |  | GRASS                      |
|               |  | EXISTING PEDESTRIAN SIGNAL      |  | DETECTABLE WARNING SURFACE |

**The Temple Group, Inc.**

1120 Connecticut Avenue, NW  
 Suite 310  
 Washington, DC 20036  
 Ph.: 202-822-6600  
 Fax: 202-822-6603  
 www.thetemplegroup.com

| No.       | DESCRIPTION | NAME | DATE |
|-----------|-------------|------|------|
| REVISIONS |             |      |      |
|           |             |      |      |
|           |             |      |      |
|           |             |      |      |



**CONSTRUCTION NOTES:**

1. REMOVE AND REPLACE RAMP
2. REMOVE AND REPLACE RAMP WITH DIRECTIONAL RAMP
3. REMOVE AND REPLACE RAMP WITH 5' LONG DIRECTIONAL RAMP
4. REPAIR AND REPLACE PCC SIDEWALK, 17' X 13'
5. ADD POROUS FLEXIBLE PAVING, 18' X 6'
6. REPAIR AND REPLACE PCC SIDEWALK, 15' X 6'
7. REPAIR AND REPLACE PCC SIDEWALK, 24' X 6'
8. REPAIR AND REPLACE PCC SIDEWALK, 15' X 6'
9. REPAIR AND REPLACE PCC SIDEWALK, 50' X 5'
10. ADD PCC SIDEWALK, 40' X 6'



|               |                                 |                            |
|---------------|---------------------------------|----------------------------|
| <b>LEGEND</b> | EXISTING CONDITIONS             | PCC SIDEWALK               |
|               | PROPOSED CONDITIONS             | BRICK SIDEWALK             |
|               | EXISTING TRAFFIC SIGNAL CABINET | GRASS                      |
|               | EXISTING PEDESTRIAN SIGNAL      | DETECTABLE WARNING SURFACE |

**The Temple Group, Inc.**  
 1120 Connecticut Avenue, NW  
 Suite 310  
 Washington, DC 20036  
 Ph.: 202-822-6600  
 Fax: 202-822-6603  
 www.thetemplegroup.com

| No.       | DESCRIPTION | NAME | DATE |
|-----------|-------------|------|------|
| REVISIONS |             |      |      |

|  |                      |
|--|----------------------|
| DISTRICT OF COLUMBIA<br>DEPARTMENT OF TRANSPORTATION<br>INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION |                      |
| <b>CITY-WIDE AMERICANS WITH<br/>         DISABILITIES ACT COMPLIANCE</b><br>DCKA-2011-C-0059             |                      |
| 7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE<br>BUS STOP #1001960, 1001966,<br>1002104, 1002028, 1002035    |                      |
| PROJECT ENG. <u>AK</u>   | DESIGN BY <u>AK</u>  |
| CHECKED BY <u>AK</u>   | DRAWN BY <u>VMD</u>  |
| FILE _____   | DATE <u>02/28/14</u> |
| SHEET <u>03 OF 03</u>  | DWG NO. _____        |