

- CONSTRUCTION NOTES:**
1. REMOVE AND REPLACE RAMP
 2. REMOVE AND REPLACE RAMP WITH 5' LONG RAMP
 3. REPAIR AND REPLACE PCC SIDEWALK, 18' X 15'
 4. REPAIR AND REPLACE PCC SIDEWALK, 16' X 15'
 5. ADD PCC SIDEWALK, 30' X 6'
 6. ADD PCC SIDEWALK, 21' X 5'
 7. REPAIR AND REPLACE PCC SIDEWALK, 19' X 16'
 8. REPAIR AND REPLACE PCC SIDEWALK, 101' X 6'
 9. ADD PCC SIDEWALK, 50' X 1.5'
 10. REPAIR AND REPLACE PCC SIDEWALK, 15' X 5'
 11. ADD PCC SIDEWALK, 7' X 2'



LEGEND	EXISTING CONDITIONS	PCC SIDEWALK
	PROPOSED CONDITIONS	BRICK SIDEWALK
	EXISTING TRAFFIC SIGNAL CABINET	GRASS
	EXISTING PEDESTRIAN SIGNAL	DETECTABLE WARNING SURFACE

The Temple Group, Inc.
 1120 Connecticut Avenue, NW
 Suite 310
 Washington, DC 20036
 Ph.: 202-822-6600
 Fax: 202-822-6603
 www.thetemplegroup.com


No.	DESCRIPTION	NAME	DATE
REVISIONS			

DISTRICT OF COLUMBIA
 DEPARTMENT OF TRANSPORTATION
 INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION

**CITY-WIDE AMERICANS WITH
 DISABILITIES ACT COMPLIANCE**
 DCKA-2011-C-0059

7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE
 BUS STOP #1001960, 1001966,
 1002104, 1002028, 1002035

PROJECT ENG.	AK
DESIGN BY	AK
CHECKED BY	AK
DRAWN BY	VMD
FILE	
DATE	02/28/14
SHEET	01 OF 03
DWG NO.	



HOLY REDEEMER
COLLEGE

CENTRO MARIA
RELIGIOUS OF
MARY IMMACULATE

7TH ST.

7TH ST.

BUS STOP #1002028

BUS STOP #1002035

7TH ST.

2

2

4

SMALL STONE FENCE

IRVING ST.

9

8

2

2

JACKSON ST.

JACKSON ST.

4

5

1

2

2

6

7



CONSTRUCTION NOTES:

1. REMOVE AND REPLACE RAMP WITH DIRECTIONAL RAMP
2. REMOVE AND REPLACE RAMP WITH 5' LONG DIRECTIONAL RAMP
3. REPAIR AND REPLACE PCC SIDEWALK, 12' X 12'
4. REPAIR AND REPLACE PCC SIDEWALK, 14' X 13'
5. REPAIR AND REPLACE PCC SIDEWALK, 14' X 14'
6. REPAIR AND REPLACE PCC SIDEWALK, 16' X 12'
7. ADD PCC SIDEWALK, 40' X 6'
8. REPAIR AND REPLACE PCC SIDEWALK, 47' X 12'
9. ADD PCC SIDEWALK, 20' X 6'

DISTRICT OF COLUMBIA
DEPARTMENT OF TRANSPORTATION
INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION

**CITY-WIDE AMERICANS WITH
DISABILITIES ACT COMPLIANCE**
DCKA-2011-C-0059

7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE
BUS STOP #1001960, 1001966,
1002104, 1002028, 1002035


PROJECT ENG. AK
DESIGN BY AK
CHECKED BY AK
DRAWN BY VMD

FILE _____
DATE 02/28/14
SHEET 02 OF 03
DWG NO. _____

LEGEND	EXISTING CONDITIONS	PCC SIDEWALK
	PROPOSED CONDITIONS	BRICK SIDEWALK
	EXISTING TRAFFIC SIGNAL CABINET	GRASS
	EXISTING PEDESTRIAN SIGNAL	DETECTABLE WARNING SURFACE

The Temple Group, Inc.
1120 Connecticut Avenue, NW
Suite 310
Washington, DC 20036
Ph.: 202-822-6600
Fax: 202-822-6603
www.thetemplegroup.com

No.	DESCRIPTION	NAME	DATE
REVISIONS			



CONSTRUCTION NOTES:

1. REMOVE AND REPLACE RAMP
2. REMOVE AND REPLACE RAMP WITH DIRECTIONAL RAMP
3. REMOVE AND REPLACE RAMP WITH 5' LONG DIRECTIONAL RAMP
4. REPAIR AND REPLACE PCC SIDEWALK, 17' X 13'
5. ADD POROUS FLEXIBLE PAVING, 18' X 6'
6. REPAIR AND REPLACE PCC SIDEWALK, 15' X 6'
7. REPAIR AND REPLACE PCC SIDEWALK, 24' X 6'
8. REPAIR AND REPLACE PCC SIDEWALK, 15' X 6'
9. REPAIR AND REPLACE PCC SIDEWALK, 50' X 5'
10. ADD PCC SIDEWALK, 40' X 6'



LEGEND	EXISTING CONDITIONS	PCC SIDEWALK
	PROPOSED CONDITIONS	BRICK SIDEWALK
	EXISTING TRAFFIC SIGNAL CABINET	GRASS
	EXISTING PEDESTRIAN SIGNAL	DETECTABLE WARNING SURFACE

The Temple Group, Inc.
 1120 Connecticut Avenue, NW
 Suite 310
 Washington, DC 20036
 Ph.: 202-822-6600
 Fax: 202-822-6603
 www.thetemplegroup.com

No.	DESCRIPTION	NAME	DATE
REVISIONS			

DISTRICT OF COLUMBIA DEPARTMENT OF TRANSPORTATION INFRASTRUCTURE PROJECT MANAGEMENT ADMINISTRATION	
CITY-WIDE AMERICANS WITH DISABILITIES ACT COMPLIANCE DCKA-2011-C-0059	
7TH ST. FROM HAMLIN ST. TO KEARNY ST., NE BUS STOP #1001960, 1001966, 1002104, 1002028, 1002035	PROJECT ENG. <u>AK</u> DESIGN BY <u>AK</u> CHECKED BY <u>AK</u> DRAWN BY <u>VMD</u> FILE _____ DATE <u>02/28/14</u> SHEET <u>03 OF 03</u> DWG NO. _____